

Maxim Crane Works, LP

5 Year Maintenance History Summary

1245

100 ton

DEMAG AC205

1995

Maxim performs scheduled Preventative Maintenance ("PMs) procedures at least every 90 days and more periodically depending on crane usage. Maxim performs a comprehensive crane inspection at each PM interval, before and after each crane rental and annually in accordance with OSHA and ANSI requirements. Maxim installed its computerized maintenance management system in 2004, attached is a standard cost summary of workorders documented since system installation. All workorders exceeding \$10,000, representing rebuild activities and major component replacement, are attached for review.

Region	Unit #	Type	WO #	Date Closed	Labor Code	WO Description	\$ Parts	\$ Labor	\$ Total
SER	1245	HYD	1015	4/30/2003	ELECTRICAL	R REAR OUTRIGGER WON'T RETRACT	-	840	840
SER	1245	HYD	1393	4/30/2003	ELECTRICAL	SERVICE CALL SUSPENSION PROBLEM	-	1,272	1,272
SER	1245	HYD	2409	7/3/2003	HYDRAULIC	SERVICE CALL TO REP BLOWN STEERING LINE,SERVICE CA	124	1,224	1,348
SER	1245	HYD	5079	7/14/2003	HYDRAULIC	SERVICE CALL FOR PTO PUMP FAILURE	798	1,752	2,550
SER	1245	HYD	7508	8/20/2003	BRAKES	SERVICE CALL TO REP SWING BRAKE	-	288	288
SER	1245	HYD	9499	9/11/2003	ELECTRICAL	A2B INOP, ENGINE OIL LEAK, AIR LEAK	228	720	948
SER	1245	HYD	17815	11/21/2003	INSPECTIONS	ATB INOPT, REP MISC OIL AND HYD LEAKS,SERVICE UNIT	5,290	6,600	11,890
SER	1245	HYD	27282	2/18/2004	HEATING AND AIR CONDITIONING	HEATER INOPT,MISC REP,WINCH PROBLEMS,MISC LEAKS	774	5,592	6,366
SER	1245	HYD	45534	3/17/2004	BOOM	REPLACE DAMAGED TIP SHEAVE	367	288	655
SER	1245	HYD	41625	3/17/2004	HEATING AND AIR CONDITIONING	LOWER HEATER BURNT UP,PM SERVICE DUE	873	1,416	2,289
SER	1245	HYD	49131	3/24/2004	TIRES	RIGHT # 3 AND LEFT # 3 TIRES NEEDS REPLACING	2,150	-	2,150
SER	1245	HYD	47769	4/14/2004	ENGINE	ENGINE OIL LEAKS,FUEL LEAK,MISC	326	1,884	2,210
SER	1245	HYD	53724	6/24/2004	HOIST / WINCH	CHANGE WINCH OIL PER OIL SAMPLE,ALT NOT CHARGING,	731	936	1,667
SER	1245	HYD	73793	8/5/2004	HYDRAULIC	HYD LEAK ON FAN DRIVE MOTOR	667	456	1,123
SER	1245	HYD	78201	9/15/2004	TIRES	C-4, TIRES WORN,CK ENGINE OIL LEAK,WON'T CRANK,	2,587	1,056	3,643
SER	1245	HYD	83789	9/27/2004	ELECTRICAL	REP CAB FAN	-	48	48
SER	1245	HYD	86751	10/12/2004	PREVENTATIVE MAINTENANCE	PM SERVICE DUE	18	240	258
SER	1245	HYD	85302	10/13/2004	HYDRAULIC	HYD PUMP ENGAGING PROBLEMS,WORN LR AND RR TIRES.	2,435	168	2,603
SER	1245	HYD	87369	10/26/2004	ELECTRICAL	SERVICE CALL ALT NOT CHARGING	250	636	886
SER	1245	HYD	94004	12/3/2004	ELECTRICAL	LOST ELECTRICAL POWER,ENGINE WATER LEAK	-	528	528
SER	1245	HYD	99061	1/20/2005	CAB	UPPER CAB DOOR LATCH BROKE,HOUSE LOCK CABLE BROKE,	127	672	799
SER	1245	HYD	106866	2/14/2005	TIRES	LEFT FRT AND RIGHT REAR TIRES NEED REPLACING.	2,590	240	2,830
SER	1245	HYD	106665	2/22/2005	CAB	CAB SHOCK	-	108	108
SER	1245	HYD	111905	4/8/2005	INSPECTIONS	CHECK HOIST CABLE AND LEAKING OUTRIGGER STAB	3,794	3,132	6,926
SER	1245	HYD	125748	4/27/2005	INSPECTIONS	ANNUAL INSPECTION	-	192	192
SER	1245	HYD	125840	4/29/2005	INSPECTIONS	DOT	45	-	45
SER	1245	HYD	109386	4/29/2005	PREVENTATIVE MAINTENANCE	PM-A SERVICE	1,044	1,032	2,076
SER	1245	HYD	130006	5/19/2005	ENGINE	TURBO SEAL LEAKING INTERNAL	17	288	305
SER	1245	HYD	130952	5/31/2005	COMPUTER SYSTEMS	PROXIMITY SWITCH MALFUNCTION	21	168	189
SER	1245	HYD	134503	6/17/2005	ENGINE	RADIATOR OVER FLOW BOTTLE CRACKED RESERVOIR	137	48	185
SER	1245	HYD	131631	6/20/2005	TIRES	LEFT SIDE CENTER TIRE BALD	2,109	-	2,109
SER	1245	HYD	137432	6/30/2005	BRAKES	AIR PUMP ON ENGINE NOT PRODUCING AIR LOCKED DOWN O	108	576	684
SER	1245	HYD	142529	8/9/2005	PREVENTATIVE MAINTENANCE	PMA SERVICE	183	384	567
SER	1245	HYD	142528	8/12/2005	COMPUTER SYSTEMS	COUNTER WEIGHT LOCKIN BLOWING FUSE'S	31	696	727
SER	1245	HYD	153147	11/28/2005	ENGINE	NO START UPPER OR LOWER	3,477	1,692	5,169
SER	1245	HYD	150347	12/15/2005	PREVENTATIVE MAINTENANCE	CHANGE HYDRALIC OIL PER OIL SAMPLE	137	48	185
SER	1245	HYD	174424	12/16/2005	PREVENTATIVE MAINTENANCE	PMA SERVICE AFTER REPAIR	227	192	419
SER	1245	HYD	172921	12/16/2005	CAB	REPAIR UPPER DOOR SLIDE AND OUTRIGGER PADS	-	912	912
SER	1245	HYD	177144	12/30/2005	TIRES	FLAT TIRE ON ROAD	195	-	195
SER	1245	HYD	169894	6/23/2006	FRAME AND CHASSIS	TOTAL RECONDITION OF UNIT	156,273	83,666	239,938
SER	1245	HYD	218364	7/3/2006	COMPUTER SYSTEMS	LABOR LEFT OFF ORG WO # 169894 APPROVED PER ROB	723	-	723
SER	1245	HYD	215855	7/5/2006	ELECTRICAL	CHECK ELECTRICAL	57	293	350
SER	1245	HYD	218750	7/5/2006	ELECTRICAL	PARTS LEFT OFF WO # 169894 OK PER JOBY	1,090	-	1,090
SER	1245	HYD	216962	7/6/2006	TIRES	TIRE PICKED UP A PIECE OF STEEL ON ROAD	1,775	-	1,775
SER	1245	HYD	219557	7/21/2006	HEATING AND AIR CONDITIONING	CHECK A/C IN DRIVERS CAB (FREEZING UP)	-	96	96
SER	1245	HYD	222355	7/21/2006	TIRES	TIRE BLOWN OUT	167	-	167
SER	1245	HYD	227431	8/17/2006	ELECTRICAL	BATTERY DEAD WILL NOT START	108	48	156
SER	1245	HYD	226427	8/25/2006	BOOM	BOOM CREEPS BACK IN WHEN EXTENDED	240	1,488	1,728
SER	1245	HYD	231415	9/1/2006	PREVENTATIVE MAINTENANCE	PM SERVICE DUE/ CHECK LOSS OF POWER	22	384	406
SER	1245	HYD	248590	11/16/2006	TIRES	LEFT REAR TIRE KEEPS LEAKING DOWN	176	-	176
SER	1245	HYD	250824	12/1/2006	PREVENTATIVE MAINTENANCE	PM SERVICE IS DUE	66	192	258
SER	1245	HYD	255118	12/20/2006	ELECTRICAL	PUMP KEEPS KICKING OU AND WON'T LET YOU OPERATE CO	-	144	144

Region	Unit #	Type	WO #	Date Closed	Labor Code	WO Description	\$ Parts	\$ Labor	\$ Total
SER	1245	HYD	253625	2/2/2007	ELECTRICAL	ATB WORKS INTERMITTENTLY	200	408	608
SER	1245	HYD	271363	3/19/2007	PREVENTATIVE MAINTENANCE	PM SERVICE IS DUE	66	264	330
SER	1245	HYD	268710	3/19/2007	FRAME AND CHASSIS	BOLTS ARE MISSING AND SOME BROKEN OFF ON STEERING	318	1,512	1,830
SER	1245	HYD	278970	4/27/2007	ELECTRICAL	UPPER FUNCTIONS & SUSPENSION NOT WORKING	-	96	96
SER	1245	HYD	280892	5/1/2007	CAB	UPPER DOOR LATCH WILL NOT OPEN DOOR FROM THE OUTSI	12	96	108
SER	1245	HYD	287771	6/5/2007	INSPECTIONS	ANNUAL CRANE INSPECTION IS DUE	-	192	192
SER	1245	HYD	287845	6/8/2007	INSPECTIONS	DOT INSPECTION IS DUE	28	216	244
SER	1245	HYD	288457	6/12/2007	HYDRAULIC	HYDRAULIC FUNCTIONS CEASED	337	876	1,213
SER	1245	HYD	291611	7/11/2007	TIRES	CRANE NEEDS SPARE TIRE TOOK TO JOBSITE AND INSTALL	-	288	288
SER	1245	HYD	284268	7/12/2007	HEATING AND AIR CONDITIONING	A/C NOT COOLING LIKE IT SHOULD/SAFETY LATCH ON BLO	3	744	747
SER	1245	HYD	296120	7/19/2007	PREVENTATIVE MAINTENANCE	PM SERVICE DUE	158	456	614
SER	1245	HYD	298410	7/31/2007	ENGINE	CHECK FOR OIL LEAKS AND STEAM CLEAN UNIT AFTER REP	-	120	120
SER	1245	HYD	294947	7/31/2007	ELECTRICAL	ATB INOPT, CT.WT CONTROL INOPT FROM CAB, LOWER A/C	288	1,170	1,458
SER	1245	HYD	296924	7/31/2007	TIRES	TIRE BLEW OUT ON 2ND AXLE FROM FRONT ON LEFT	2,255	-	2,255
SER	1245	HYD	295229	8/3/2007	INSPECTIONS	INSPECT UNIT AND WRITE UP REPORT PER RON EICKHOFF	-	377	377
SER	1245	HYD	300372	8/8/2007	PREVENTATIVE MAINTENANCE	PULL OIL SAMPLE ON #2 AXLE DROP BOX,DRAIN OIL	-	135	135
SER	1245	HYD	300391	8/10/2007	DRIVE TRAIN	METAL IS GETTING INTO DROP BOX /FRONT DIFF. WE BEL	-	240	240
SER	1245	HYD	301243	8/21/2007	HEATING AND AIR CONDITIONING	SEAL BLOWN IN LOWER CAB A/C PUMP	16	408	424
SER	1245	HYD	307823	9/21/2007	PNEUMATIC SYSTEMS	SERVICE CALL TO REP BLOWN AIR LINE	58	135	193
SER	1245	HYD	312182	10/11/2007	COMPUTER SYSTEMS	SCREEN FOR COMPUTER WENT BLANK	-	240	240
SER	1245	HYD	316758	10/26/2007	ELECTRICAL	CYLINDERS THAT PICK UP THE COUNTERWEIGHTS IS NOT W	-	144	144
SER	1245	HYD	315200	10/26/2007	HYDRAULIC	HYD LINE BUSTED INSIDE OUTRIGGER BOX	635	1,785	2,420
SER	1245	HYD	310633	10/30/2007	ELECTRICAL	RIGHT BRAKE LIGHT IS OUT	83	96	179
SER	1245	HYD	320080	11/15/2007	HYDRAULIC	FLUID LEAKING FROM UNDER CRANE	-	120	120
SER	1245	HYD	319557	11/15/2007	PREVENTATIVE MAINTENANCE	PM SERVICE IS DUE	48	360	408
SER	1245	HYD	321482	12/7/2007	PREVENTATIVE MAINTENANCE	TAKE AN OIL SAMPLE FROM HYDRAULICS AND SEND OFF TO	-	12	12
SER	1245	HYD	325032	12/28/2007	ENGINE	FUEL LEAK NEAR FUEL FILTERS	-	288	288
SER	1245	HYD	326005	1/7/2008	FRAME AND CHASSIS	REP CT WT PINNING SYSTEM	460	600	1,060
SER	1245	HYD	318612	1/11/2008	ELECTRICAL	NEEDS HEATER IN UPPER CAB	-	48	48
SER	1245	HYD	330563	1/11/2008	ENGINE	COOLANT LEAK UNDERNEATH CRANE	-	216	216
SER	1245	HYD	340690	2/15/2008	ELECTRICAL	WON'T START ON YARD/ BATTERIES DEAD	-	72	72
SER	1245	HYD	330955	2/16/2008	HYDRAULIC	CHECK SMALL HYD LEAKS AT L.R. OUTRIGGER CYLINDER A	212	252	464
SER	1245	HYD	341798	2/16/2008	OUTRIGGERS	NEEDS NEW RIGGING ASSY USED FOR SETTING THE OUTRIG	503	-	503
SER	1245	HYD	343090	2/27/2008	PREVENTATIVE MAINTENANCE	PM SERVICE IS DUE	20	756	776
SER	1245	HYD	342305	2/27/2008	BOOM	CHECK COUNTERWEIGHT LOCKING SYSTEM .	393	384	777
SER	1245	HYD	345289	3/5/2008	TIRES	R.F. TIRE AND 2ND TIRE ON RIGHT FRONT BOTH HAVE SL	218	-	218
SER	1245	HYD	345380	3/7/2008	ELECTRICAL	AFTER TURNING ENGINE OFF IT WOULD NOT START BACK U	5	108	113
SER	1245	HYD	345344	3/7/2008	ELECTRICAL	R.R. TAILLIGHT IS OUT	-	144	144
SER	1245	HYD	347659	3/20/2008	FRAME AND CHASSIS	2ND FROM REAR HUB ON RIGHT SIDE STARTED SMOKING	3,013	1,416	4,429
SER	1245	HYD	357594	5/15/2008	ELECTRICAL	UPPER CAB ELECTRICAL IS STAYING ON AFTER YOU SWITC	75	60	135
SER	1245	HYD	359194	5/30/2008	ELECTRICAL	OPERATOR LEFT KEY ON AND KILLED BATTERIES	-	168	168
SER	1245	HYD	345682	6/6/2008	BRAKES	SWING BRAKE ISN'T HOLDING LIKE IT SHOULD	102	480	582
SER	1245	HYD	353948	6/6/2008	FRAME AND CHASSIS	REPLACE ALL OF THE BOLTS THAT HOLD THE STEERING AR	153	468	621
SER	1245	HYD	361124	6/23/2008	BILLABLE	CRANE IS AT JOBSITE AND WAS LIFTING OVER THE REAR	309	2,568	2,877
SER	1245	HYD	374738	10/21/2008	PREVENTATIVE MAINTENANCE	PERFORM 1000HR PM ON UNIT	632	390	1,022
SER	1245	HYD	364590	11/19/2008	BOOM	REPAIR DAMAGES TO CRANE BOOM AND JIB ETC. AFTER IT	107,220	11,109	118,329
SER	1245	HYD	390255	12/12/2008	BOOM	INSTALL JIB ON CRANE AND ADJUST TO FIT LIKE IT SHO	-	984	984
SER	1245	HYD	394816	1/12/2009	TIRES	L.R.TIRE FLAT	167	192	359
SER	1245	HYD	396545	1/26/2009	ELECTRICAL	WON'T START ON YARD/ BATTERIES DEAD	328	192	520
SER	1245	HYD	398428	2/2/2009	INSPECTIONS	D.O.T.INSPECTION	-	144	144
SER	1245	HYD	396711	2/2/2009	OUTRIGGERS	R.F.VERT O.R.LEAKING	697	288	985
SER	1245	HYD	402031	2/26/2009	RIGGING	RIGGING FOR UNIT	587	-	587

Region	Unit #	Type	WO #	Date Closed	Labor Code	WO Description	\$ Parts	\$ Labor	\$ Total
SER	1245	HYD	405320	3/17/2009	ELECTRICAL	S/C UNIT WON'T CRANK	-	90	90
SER	1245	HYD	406746	4/3/2009	RIGGING	MATTS FOR CRANE PER CHARLIE	1,824	-	1,824
SER	1245	HYD	406504	4/14/2009	ELECTRICAL	ALTERNATOR LIGHT CAME ON AND NO GAUGES ARE WORKING	557	1,392	1,949
SER	1245	HYD	410858	4/16/2009	ELECTRICAL	S/C HYD'S WILL NOT ENGAGE FOR UPPER	-	312	312
SER	1245	HYD	413205	4/29/2009	RIGGING	RIGGING FOR UNIT PER KEITH	1,108	-	1,108
SER	1245	HYD	413983	5/6/2009	ELECTRICAL	REPAIRS TO ELEC AND STARTING SYSTEM BY SEPERIOR	619	-	619
SER	1245	HYD	414492	5/12/2009	OUTRIGGERS	REPAIR O/R PADS	-	72	72
SER	1245	HYD	413801	5/12/2009	TIRES	R.F. TIRE HAS A SLOW LEAK	169	-	169
SER	1245	HYD	414738	5/19/2009	PNEUMATIC SYSTEMS	REAR BRAKE LOCKING UP (AIR LEAK AT BRAKE CHAMBER)	501	408	909
SER	1245	HYD	415977	5/26/2009	BRAKES	POSITIVE SWING BRAKE WILL NOT HOLD	-	248	248

Work Order Estimate

Work Order #	17815
Branch	AUG
Bill to Branch	AUG
Customer Number	0
Equipment Model	AC205
Equipment Class	100
Description of Problem	DIFF FAILURE #4 AXLE, REP BRAKES 119967 KM
Work Order Desc.	ATB INOPT, REP MISC OIL AND HYD LEAKS,SERVICE UNIT
Reviewed by	
Reviewers Comments	
Review Date	

Authorized By	
Authorized Date	
Created By	JOBYG
Date Opened	10/02/2003
Equipment Number	1245
Equipment Make	DEMAG
Equipment Category	60

	<i>Estimate</i>	<i>Actual</i>
Labor Total \$	\$0.00	\$7,176.00
Parts Total \$	\$0.00	\$5,289.67
Misc Charge	\$0.00	\$0.00
Total \$	\$0.00	\$12,465.67

Labor

Labor					
		0	\$0.00	137.5	\$7,176.00
Totals:		0	\$0.00	137.5	\$7,176.00

Parts

Parts					
	P18 O RING S	0	\$0.00	23	\$74.86
BG	BEARING	0	\$0.00	1	\$16.27
DT	DRIVETRAIN	0	\$0.00	1	\$4,261.35
EL	ELECTRICAL	0	\$0.00	4	\$12.00
FL	FILTER	0	\$0.00	4	\$0.00
HW	HARDWARE	0	\$0.00	18	\$33.31
SK	SEAL KIT	0	\$0.00	4	\$830.60
SL	SEAL	0	\$0.00	9	\$61.28
Totals:		0	\$0.00	64	\$5,289.67

Other

Other					
	Nothing Found				
Totals:					

Work Order Estimate

Work Order #	169894
Branch	RBS
Bill to Branch	RBS
Customer Number	0
Equipment Model	AC205
Equipment Class	100
Description of Problem	OLD HR METER HAD 13,600HRS
Work Order Desc.	TOTAL RECONDITION OF UNIT
Reviewed by	
Reviewers Comments	
Review Date	

Authorized By	Approved Dennis Wagner
Authorized Date	
Created By	JOBYG
Date Opened	12/08/2005
Equipment Number	1245
Equipment Make	DEMAG
Equipment Category	60

	<i>Estimate</i>	<i>Actual</i>
Labor Total \$	\$84,720.00	\$77,730.00
Parts Total \$	\$148,000.00	\$156,943.61
Misc Charge	\$0.00	\$0.00
Total \$	\$232,720.00	\$234,673.61

Labor

5110	CRANE DISASSEMBLY	200	\$6,000.00	208.5	\$6,412.50
5644	RECONDITION LOWER CAB	180	\$5,400.00	122	\$3,690.00
5645	RECONDITION UPPER CAB	180	\$5,400.00	128	\$3,930.00
5654	PREP AND PAINT SHEET METAL, BOOM & MISC PARTS	450	\$13,500.00	436	\$13,140.00
5671	RECONDITION AIR SYSTEMS	40	\$1,200.00	32	\$960.00
5706	REPAIR SHEET METAL	60	\$1,800.00	72	\$2,160.00
5876	INITIAL INSPECTION & ESTIMATE	0	\$0.00	0	\$0.00
5877	ESTIMATE APPROVAL	0	\$0.00	0	\$0.00
5880	REPAIR/REPLACE ENGINE LOWER	120	\$3,600.00	104.5	\$3,202.50
5881	REPAIR/REPLACE/RECONDITION TRANSMISSION	60	\$1,800.00	21.5	\$667.50
5882	RECONITION CHASSIS	300	\$9,000.00	253.5	\$7,642.50
5883	RECONDITION HYDRAULIC SYSTEM	350	\$10,500.00	322.5	\$9,847.50
5884	REPAIR/RECONDITION SLEWING GEAR	40	\$1,200.00	16	\$480.00
5885	RECONDITION ELECTRICAL SYSTEM	200	\$6,000.00	247.5	\$7,477.50
5886	REPAIR/REPLACE BOOM	250	\$7,500.00	213.5	\$6,427.50
5887	REPAIR/REPLACE FRONT WINCH	60	\$1,800.00	48	\$1,440.00
5889	REPAIR/UPGRADE COMPUTER SYSTEM	60	\$1,800.00	99.5	\$3,157.50
5890	CRANE REASSEMBLY	250	\$7,500.00	236	\$7,095.00
5891	FINAL INSPECTION AND RECERTIFICATION	24	\$720.00	0	\$0.00
Totals:		2824	\$84,720.00	2,561	\$77,730.00

Parts

	BOX LEVEL	8	\$148,000.00	1	\$65.00
	OUTSIDE REBUILD	0	\$0.00	1	\$55.00
	OUTSIDE REBUILD	0	\$0.00	1	\$95.00
	OUTSIDE REBUILD	0	\$0.00	1	\$840.00
	OUTSIDE REBUILD	0	\$0.00	1	\$1,115.00
	OUTSIDE REBUILD	0	\$0.00	1	\$5,000.00
	OUTSIDE REBUILD	0	\$0.00	1	\$8,046.54
	OUTSIDE REBUILD	0	\$0.00	1	\$2,950.00
	OUTSIDE REBUILD	0	\$0.00	1	\$1,142.05
	OUTSIDE REBUILD	0	\$0.00	1	\$118.72
	OUTSIDE REBUILD	0	\$0.00	1	\$967.88
	OUTSIDE REBUILD	0	\$0.00	1	\$238.24
	OUTSIDE REBUILD	0	\$0.00	1	\$190.00
	SMALL TOOLS PURCHASE OR TOOL RENTAL	0	\$0.00	1	\$19.95
	OUTSIDE REBUILD	0	\$0.00	1	\$297.28
	FABRICATION/WELDING SERVICES	0	\$0.00	1	\$155.00
	FREIGHT ON PARTS	0	\$0.00	1	\$8.95

	OUTSIDE REBUILD	0	\$0.00	1	\$251.60
	OUTSIDE REBUILD	0	\$0.00	1	\$342.92
	OUTSIDE REBUILD	0	\$0.00	1	\$869.09
	OUTSIDE REBUILD	0	\$0.00	5	\$375.00
	TIRE REPAIR	0	\$0.00	1	\$75.00
	OUTSIDE REBUILD	0	\$0.00	1	\$350.00
	FREIGHT ON PARTS	0	\$0.00	1	\$961.17
BG	BEARING	0	\$0.00	50	\$3,002.19
BL	BELT	0	\$0.00	1	\$23.18
BP	HYD BOOM PARTS	0	\$0.00	4	\$1,290.62
BR	BRAKES	0	\$0.00	25	\$12,933.59
BT	BATTERY	0	\$0.00	2	\$282.32
CA	CARRIER	0	\$0.00	5	\$2,906.51
CB	CABLE ASSEMBLY	0	\$0.00	44	\$433.31
CD	CAB AND DOORS	0	\$0.00	6	\$577.17
CH	CHEMICALS	0	\$0.00	12	\$42.00
CM	COMPUTER	0	\$0.00	1	\$2,389.63
DC	DECALS	0	\$0.00	27	\$196.82
DT	DRIVETRAIN	0	\$0.00	2	\$902.60
EL	ELECTRICAL	0	\$0.00	134	\$21,098.61
EN	WHOLE ENGINES	0	\$0.00	1	\$22,479.00
EP	ENGINE PARTS	0	\$0.00	11	\$3,112.57
FL	FILTER	0	\$0.00	17	\$1,490.62
FT	FITTINGS	0	\$0.00	163	\$2,005.06
GL	GLASS & MIRRORS	0	\$0.00	2	\$11.16
GS	GASKET	0	\$0.00	9	\$72.71
HB	HYD BOOM CYLINDER	0	\$0.00	2	\$988.60
HC	HYDRAULIC COMPONENTS	0	\$0.00	70	\$10,741.63
HS	HOSES	0	\$0.00	343	\$3,847.33
HW	HARDWARE	0	\$0.00	680	\$12,657.45
LT	LIGHTS	0	\$0.00	87	\$477.03
MS	MISCELLANEOUS	0	\$0.00	10	\$104.10
PT	PAINT	0	\$0.00	3	\$5,544.04
SG	SAFETY GEAR	0	\$0.00	5	\$15.50
SK	SEAL KIT	0	\$0.00	32	\$9,077.30
SL	SEAL	0	\$0.00	92	\$1,547.35
SN	SUSPENSION	0	\$0.00	2	\$223.16
SP	SHOP SUPPLIES	0	\$0.00	4	\$91.00
SV	SHEAVE	0	\$0.00	5	\$1,767.99
TI	TIRES	0	\$0.00	5	\$8,875.00
VV	VALVES	0	\$0.00	3	\$327.26
WL	WELDING SUPPLIES	0	\$0.00	1	\$41.63
WR	WIRE ROPE	0	\$0.00	2	\$838.18
Totals:		8	\$148,000.00	1,890	\$156,943.61

Other

	Nothing Found			
Totals:				

Work Order Estimate

Work Order #	364590
Branch	COL
Bill to Branch	COL
Customer Number	0
Equipment Model	AC205
Equipment Class	100
Description of Problem	FLIPPED OVER.I CLOSE ORIGINAL WORKORDER #361124 AFTR WE HAD GOTTEN THE CRANE BACK UP AND TO THE SHOP. ADDED STEP TO INSPECT UNIT AT RBS
Work Order Desc.	REPAIR DAMAGES TO CRANE BOOM AND JIB ETC. AFTER IT
Reviewed by	
Reviewers Comments	
Review Date	

Authorized By	Approved RentalMan
Authorized Date	
Created By	JULIANB
Date Opened	06/25/2008
Equipment Number	1245
Equipment Make	DEMAG
Equipment Category	60

	Estimate	Actual
Labor Total \$	\$0.00	\$17,352.00
Parts Total \$	\$0.00	\$107,219.69
Misc Charge	\$0.00	\$0.00
Total \$	\$0.00	\$124,571.69

Labor

Code	Description	Rate	Unit	Hours	Total
5288	TROUBLE SHOOT COMPUTER MALFUNCTION & REPAIR	\$0.00		27.5	\$1,428.00
5385	TOUCH UP PAINT	\$0.00		111	\$5,364.00
5706	REPAIR SHEET METAL	\$0.00		32	\$1,584.00
5995	INSPECT UNIT/MAKE UP REPAIR LIST	\$0.00		6	\$336.00
6055	MAKE NEEDED REPAIRS	\$0.00		88	\$4,524.00
6142	LOAD/UNLOAD TRUCKS IN YARD	\$0.00		3	\$216.00
6294	INSTALL BOOM ASSY	\$0.00		73	\$3,900.00
Totals:		0	\$0.00	340.5	\$17,352.00

Parts

Code	Description	Rate	Unit	Quantity	Total
.	OUTSIDE BOOM REPAIR	\$0.00		1	\$40,324.65
.	OUTSIDE BOOM REPAIR	\$0.00		1	\$40,324.65
.	OUTSIDE FABRICATION	\$0.00		1	\$101.77
.	OUTSIDE HEAT/AC REPAIR	\$0.00		1	\$732.94
.	OUTSIDE FABRICATION	\$0.00		1	\$242.54
BH	HYD BOOM SECTION	\$0.00		1	\$18,848.20
EL	ELECTRICAL	\$0.00		10	\$2,240.91
EP	ENGINE PARTS	\$0.00		1	\$45.62
GS	GASKET	\$0.00		1	\$58.38
HC	HYDRAULIC COMPONENTS	\$0.00		5	\$432.01
HW	HARDWARE	\$0.00		27	\$1,958.60
LT	LIGHTS	\$0.00		8	\$66.24
PT	PAINT	\$0.00		65	\$1,480.83
SG	SAFETY GEAR	\$0.00		1	\$11.06
SL	SEAL	\$0.00		3	\$29.17
TL	TOOLS	\$0.00		2	\$47.32
VV	VALVES	\$0.00		1	\$274.80
Totals:		0	\$0.00	130	\$107,219.69

Other

Nothing Found					
Totals:					