

# Maxim Crane Works, LP

## 5 Year Maintenance History Summary

1601

300 ton

LIEBHERR LTM1225

1996

Maxim performs scheduled Preventative Maintenance ("PMs) procedures at least every 90 days and more periodically depending on crane usage. Maxim performs a comprehensive crane inspection at each PM interval, before and after each crane rental and annually in accordance with OSHA and ANSI requirements. Maxim installed its computerized maintenance management system in 2004, attached is a standard cost summary of workorders documented since system installation. All workorders exceeding \$10,000, representing rebuild activities and major component replacement, are attached for review.

Region	Unit #	Type	WO #	Date Closed	Labor Code	WO Description	\$ Parts	\$ Labor	\$ Total
CER	1601	HYD	6082	7/18/2003	LOADING/UNLOADING	LOAD OUT RIGGING	-	72	72
CER	1601	HYD	6193	7/18/2003	ENGINE	FUEL FILTERS UPPER ENGINE	20	192	212
CER	1601	HYD	9888	8/7/2003	HYDRAULIC	HYDRAULIC	-	144	144
CER	1601	HYD	11275	8/29/2003	RIGGING	RIGGING	90	120	210
CER	1601	HYD	12624	9/3/2003	HYDRAULIC	HYDRAULIC LEAK ON UPPER	-	504	504
CER	1601	HYD	13568	9/4/2003	HYDRAULIC	HYDRAULIC	-	336	336
CER	1601	HYD	14388	9/17/2003	ENGINE	FUEL	20	72	92
CER	1601	HYD	16708	10/6/2003	PREVENTATIVE MAINTENANCE	SERVICE UPPER	1,667	192	1,859
CER	1601	HYD	19801	10/17/2003	ELECTRICAL	UPPER KILL SOLENOID BAD	106	168	274
CER	1601	HYD	17426	10/17/2003	HYDRAULIC	HYDRAULIC OIL LEAK	795	-	795
CER	1601	HYD	21439	10/31/2003	PAINTING	PAINT BOOM DOLLY	194	720	914
CER	1601	HYD	20332	11/12/2003	PREVENTATIVE MAINTENANCE	CHECK SUSPENSION,CHANGE FUEL FILTERS ON LOWER,MAKE	1,667	1,824	3,491
CER	1601	HYD	29004	12/15/2003	LOADING/UNLOADING	LOAD JIB	-	120	120
CER	1601	HYD	31320	1/9/2004	PREVENTATIVE MAINTENANCE	SERVICE LOWER	152	528	680
CER	1601	HYD	33593	1/16/2004	CAB	INSTALL KEY LOCK IN LOWER TOOL BOX	237	48	285
CER	1601	HYD	35588	1/29/2004	ENGINE	UPPER RUNNING ROUGH	266	48	314
CER	1601	HYD	39200	2/9/2004	ELECTRICAL	KEY BROKE OFF IN IGNITION IN UPPER	83	96	179
CER	1601	HYD	37370	2/9/2004	ELECTRICAL	LOWER WILL NOT START	168	96	264
CER	1601	HYD	39692	2/19/2004	PREVENTATIVE MAINTENANCE	SERVICE UPPER	515	336	851
CER	1601	HYD	47087	3/20/2004	LOADING/UNLOADING	LOADED JIB	-	144	144
CER	1601	HYD	47078	3/20/2004	ENGINE	OIL LEAK	-	168	168
CER	1601	HYD	47047	3/20/2004	COMPUTER SYSTEMS	AZB ON JIB NOT WORKING	355	144	499
CER	1601	HYD	51892	4/21/2004	ELECTRICAL	BEACON LAMP	60	192	252
CER	1601	HYD	54812	4/30/2004	PREVENTATIVE MAINTENANCE	SERVICE UPPER	119	288	407
CER	1601	HYD	59694	5/21/2004	INSPECTIONS	ANNUAL INSPECTION	150	-	150
CER	1601	HYD	54685	5/27/2004	HYDRAULIC	LUFFER BRAKE VALVE	2,101	168	2,269
CER	1601	HYD	64148	6/17/2004	LOADING/UNLOADING	LOAD OUT JIB	-	48	48
CER	1601	HYD	64900	6/22/2004	ELECTRICAL	LOWER WILL NOT START	171	72	243
CER	1601	HYD	66567	6/28/2004	PREVENTATIVE MAINTENANCE	MAKE READY TRIP TO AUSTIN	1,670	240	1,910
CER	1601	HYD	73062	8/6/2004	ELECTRICAL	WILL NOT SWING	1,466	238	1,705
CER	1601	HYD	81521	9/27/2004	EXHAUST	REPLACED MUFFLER ON LOWER	-	288	288
CER	1601	HYD	86358	10/29/2004	BOOM	SAFETY PIN	9	-	9
CER	1601	HYD	87444	10/29/2004	PREVENTATIVE MAINTENANCE	UPPER RUNNING ROUGH	25	96	121
CER	1601	HYD	88851	11/3/2004	TIRES	TIRES	145	-	145
CER	1601	HYD	91759	11/15/2004	ELECTRICAL	WINCH PROBLEMS	813	256	1,069
CER	1601	HYD	88955	11/20/2004	TIRES	DOLLY TIRE FLAT	81	-	81
CER	1601	HYD	94664	12/7/2004	PREVENTATIVE MAINTENANCE	SERVICE UPPER & LOWER	393	720	1,113
CER	1601	HYD	98054	1/18/2005	HYDRAULIC	HYD OIL LEAK	-	48	48
CER	1601	HYD	103504	2/16/2005	HYDRAULIC	HYDRAULICS FOR LUFFER	52	144	196
CER	1601	HYD	106900	2/21/2005	TIRES	LEFT FRONT TIRE	210	-	210
CER	1601	HYD	109573	2/26/2005	FABRICATION	STRAPS FOR AIR TANKS	-	416	416
CER	1601	HYD	114318	3/7/2005	TIRES	RF FLAT REPAIR	150	-	150
CER	1601	HYD	116844	3/28/2005	PREVENTATIVE MAINTENANCE	FIRE EXTINGUISHER - LOWER	86	16	102
CER	1601	HYD	117939	3/28/2005	INSPECTIONS	RENTAL INSPECTION	-	184	184
CER	1601	HYD	120772	4/8/2005	ENGINE	FUEL FILTERS	29	72	101
CER	1601	HYD	122145	4/14/2005	ENGINE	UPPER ENGINE BELT	69	288	357
CER	1601	HYD	121952	4/18/2005	HYDRAULIC	ENGINE OIL/HYD LEAKS	-	232	232
CER	1601	HYD	119584	4/18/2005	HYDRAULIC	BALLASTING RAMS	812	-	812
CER	1601	HYD	112033	4/28/2005	PREVENTATIVE MAINTENANCE	PM-A SERVICE DUE UPPER	157	96	253

Region	Unit #	Type	WO #	Date Closed	Labor Code	WO Description	\$ Parts	\$ Labor	\$ Total
CER	1601	HYD	124437	5/6/2005	FABRICATION	LADDER REPAIR	-	176	176
CER	1601	HYD	128061	5/6/2005	INSPECTIONS	ANNUAL INSPECTION	195	-	195
CER	1601	HYD	126315	6/2/2005	PREVENTATIVE MAINTENANCE	L.ENGINE, STEERING	1,870	256	2,126
CER	1601	HYD	129164	6/2/2005	PREVENTATIVE MAINTENANCE	REPAIRS AFTER SERVICE	3,926	600	4,526
CER	1601	HYD	122929	6/14/2005	RIGGING	RIGGING	558	-	558
CER	1601	HYD	124493	6/27/2005	PREVENTATIVE MAINTENANCE	SERVICE	1,041	112	1,153
CER	1601	HYD	128172	7/5/2005	RIGGING	JOBBOX ON PRIMARY TRAILER 6225	377	-	377
CER	1601	HYD	137870	7/8/2005	PREVENTATIVE MAINTENANCE	LOWER FUEL FILTER	11	-	11
CER	1601	HYD	140885	7/21/2005	ENGINE	FITTING LEAKING ON LOWER 4 DOLLY FREE FLOAT SYSTM	-	128	128
CER	1601	HYD	144733	8/6/2005	PREVENTATIVE MAINTENANCE	UPPER: PMB LOWER: PMB	875	240	1,115
CER	1601	HYD	144846	8/27/2005	HYDRAULIC	SMALL HYDRAULIC LEAK	205	64	269
CER	1601	HYD	148732	8/30/2005	HYDRAULIC	HYD LEAK 2 OUTRIGGERS	-	344	344
CER	1601	HYD	156863	10/12/2005	PREVENTATIVE MAINTENANCE	INSTALL A/C	1,680	-	1,680
CER	1601	HYD	164414	11/11/2005	PREVENTATIVE MAINTENANCE	GREASE BOOM	227	120	347
CER	1601	HYD	173259	12/12/2005	PREVENTATIVE MAINTENANCE	SERVICE DUE PM-A	148	120	268
CER	1601	HYD	172134	12/14/2005	HYDRAULIC	HYD HOSE BLOWN	24	256	280
CER	1601	HYD	175378	12/27/2005	ELECTRICAL	REPLACE BATTERIES IN UPPER	169	72	241
CER	1601	HYD	179218	1/11/2006	PREVENTATIVE MAINTENANCE	SERVICE UPPER PM-B	259	384	643
CER	1601	HYD	179589	1/26/2006	TIRES	REPLACE TWO TIRES, LIGHTS	4,224	72	4,296
CER	1601	HYD	137633	2/16/2006	BOOM	MAKE READY FOR SWING-A-WAY JIB FROM SAN DIEGO	4,781	128	4,909
CER	1601	HYD	201516	4/19/2006	PREVENTATIVE MAINTENANCE	SERVICE LOWER PM-A	188	144	332
CER	1601	HYD	201515	4/19/2006	PREVENTATIVE MAINTENANCE	SERVICE UPPER PM-A	143	288	431
CER	1601	HYD	205518	5/4/2006	INSPECTIONS	ANNUAL INSPECTION	195	-	195
CER	1601	HYD	207365	5/17/2006	PREVENTATIVE MAINTENANCE	SHEAVE REPAIRS	890	216	1,106
CER	1601	HYD	208624	5/23/2006	ELECTRICAL	LOWER NEEDS BATTERIES	186	120	306
CER	1601	HYD	209868	5/30/2006	HYDRAULIC	CHARGE NITROGEN IN CYL. LUFFER BUT	-	756	756
CER	1601	HYD	199549	6/20/2006	HYDRAULIC	HYDRAULIC LEAK	448	1,044	1,492
CER	1601	HYD	177843	6/23/2006	COMPUTER SYSTEMS	LUFFERBOOM ANGLE MALFUNCTIONING	350	2,136	2,486
CER	1601	HYD	172876	6/23/2006	HYDRAULIC	REPLACE SHEAVE BEARINGS	2,792	432	3,224
CER	1601	HYD	205864	7/3/2006	HYDRAULIC	LUFFING JIB MAST CYLINDER LEAKING	11,889	288	12,177
CER	1601	HYD	221813	7/20/2006	PREVENTATIVE MAINTENANCE	SERVICE PM-A UPPER	142	168	310
CER	1601	HYD	214432	7/21/2006	PREVENTATIVE MAINTENANCE	UPPER KEY BROKEN OFF	221	-	221
CER	1601	HYD	216547	7/21/2006	ELECTRICAL	LUFFING BUTT NEEDS REWIRED	2,108	696	2,804
CER	1601	HYD	217273	8/7/2006	PREVENTATIVE MAINTENANCE	UPPER EXPANSION TANK FOR COOLANT SYSTEM	620	-	620
CER	1601	HYD	226800	8/10/2006	PREVENTATIVE MAINTENANCE	INSTALL RADIATOR TANK	-	96	96
CER	1601	HYD	226954	8/14/2006	PREVENTATIVE MAINTENANCE	UPPER FUEL FILTERS	22	48	70
CER	1601	HYD	231938	9/11/2006	PREVENTATIVE MAINTENANCE	CAB FAN	35	-	35
CER	1601	HYD	230095	9/14/2006	ELECTRICAL	ELECTRICAL SHORT	-	264	264
CER	1601	HYD	236615	10/5/2006	PREVENTATIVE MAINTENANCE	REPAIR AUTOMATIC GREASER	-	84	84
CER	1601	HYD	239133	10/5/2006	PREVENTATIVE MAINTENANCE	SERVICE UPPER PM-A	148	144	292
CER	1601	HYD	231108	10/5/2006	TIRES	R2 TIRE	2,015	-	2,015
CER	1601	HYD	249791	11/21/2006	HYDRAULIC	REPLACED BUSTED HYDRAULIC HOSE	-	48	48
CER	1601	HYD	249012	11/21/2006	PREVENTATIVE MAINTENANCE	PUT IN DOLLEY	30	96	126
CER	1601	HYD	250029	12/5/2006	PREVENTATIVE MAINTENANCE	REPAIRS	3,485	384	3,869
CER	1601	HYD	252836	12/7/2006	HYDRAULIC	CHANGED QUICK DISCONNECT	-	48	48
CER	1601	HYD	239786	12/28/2006	ENGINE	UPPER ENGINE WATER LEAK	1,808	468	2,276
CER	1601	HYD	216531	12/28/2006	HYDRAULIC	COUNTERWEIGHT CYL NEED REPACKED	5,763	192	5,955
CER	1601	HYD	257116	1/3/2007	TIRES	FLAT TIRE	103	-	103
CER	1601	HYD	257111	1/3/2007	TIRES	BOOM DOLLY LFI TIRE	222	-	222

Region	Unit #	Type	WO #	Date Closed	Labor Code	WO Description	\$ Parts	\$ Labor	\$ Total
CER	1601	HYD	255146	1/9/2007	PREVENTATIVE MAINTENANCE	NEEDS ENGINE DOOR SHOCKS	159	48	207
CER	1601	HYD	262520	2/2/2007	PREVENTATIVE MAINTENANCE	SERVICE LOWER PM-B	307	168	475
CER	1601	HYD	266361	2/26/2007	COMPUTER SYSTEMS	ANGLE SENSOR ON LUFFER BUTT	2,587	324	2,911
CER	1601	HYD	269879	3/7/2007	ENGINE	ALTERNATOR BELT-UPPER	10	72	82
CER	1601	HYD	268131	3/8/2007	ELECTRICAL	ELECTRICAL PROBLEM ON LUFFER	-	180	180
CER	1601	HYD	271192	3/12/2007	ELECTRICAL	REPLACED BATTERY/ CHECK CHARGING SYSTEM	127	144	271
CER	1601	HYD	272959	3/22/2007	PREVENTATIVE MAINTENANCE	SERVICE UPPER	162	120	282
CER	1601	HYD	261468	3/28/2007	DRIVE TRAIN	CHECK TRANSFER CASE	5,409	3,024	8,433
CER	1601	HYD	275808	4/16/2007	PREVENTATIVE MAINTENANCE	NEEDS 10' LADDER	200	-	200
CER	1601	HYD	283531	5/11/2007	INSPECTIONS	ANNUAL INSPECTION	175	-	175
CER	1601	HYD	283804	5/14/2007	PAINTING	TOUCH UP PAINT	-	336	336
CER	1601	HYD	284185	5/16/2007	PAINTING	TOUCH UP PAINT (COUNTERWEIGHT CYLINDERS)	-	96	96
CER	1601	HYD	277495	5/24/2007	PREVENTATIVE MAINTENANCE	GEARBOX	4,051	2,844	6,895
CER	1601	HYD	283917	6/9/2007	HYDRAULIC	COUNTERWEIGHT CYLS.LEAK OFF	4,347	588	4,935
CER	1601	HYD	290468	6/19/2007	HYDRAULIC	FILL HYDRAULIC TANK- LOWER	-	144	144
CER	1601	HYD	293489	7/14/2007	HYDRAULIC	REPLACE HYDRAULIC FITTINGS	458	144	602
CER	1601	HYD	290782	7/14/2007	PREVENTATIVE MAINTENANCE	REPAIRS PER MECHANIC INSPECTION	1,812	300	2,112
CER	1601	HYD	295260	7/18/2007	PREVENTATIVE MAINTENANCE	LOWER FUEL FILTERS	29	96	125
CER	1601	HYD	296989	7/23/2007	PREVENTATIVE MAINTENANCE	SERVICE UPPER PM-A	188	504	692
CER	1601	HYD	296995	8/4/2007	PREVENTATIVE MAINTENANCE	AIR LEAK-OIL LEAK	-	480	480
CER	1601	HYD	295264	9/19/2007	HYDRAULIC	REPLACE WATER PUMP	2,101	1,032	3,133
CER	1601	HYD	308526	9/26/2007	HYDRAULIC	OUTRIGGER HOSES RF	288	144	432
CER	1601	HYD	304296	9/26/2007	PREVENTATIVE MAINTENANCE	REAR MUD FLAPS, TRANSFER CASE LEAK	703	168	871
CER	1601	HYD	312893	10/9/2007	ENGINE	LOWER WONT START	-	72	72
CER	1601	HYD	312318	10/15/2007	PREVENTATIVE MAINTENANCE	UPPER ENGINE SOLENOID	116	108	224
CER	1601	HYD	308575	10/19/2007	HYDRAULIC	REPLACE CLUTCH FAN ON UPPER ENGINE	4,784	168	4,952
CER	1601	HYD	314564	11/1/2007	ENGINE	UPPER ENGINE GETTING HOT	-	120	120
CER	1601	HYD	317468	11/14/2007	ENGINE	ENGINE HAS OIL LEAK	-	72	72
CER	1601	HYD	322909	11/28/2007	PREVENTATIVE MAINTENANCE	SERVICE UPPER PM-B	263	240	503
CER	1601	HYD	324113	12/7/2007	FRAME AND CHASSIS	SERVICE ACCUMULATORS	-	24	24
CER	1601	HYD	309875	12/12/2007	HYDRAULIC	BALLASTING RAM	1,329	240	1,569
CER	1601	HYD	308576	12/12/2007	BOOM	REPLACE 2 HEAD SECTION SHEAVES	5,320	1,344	6,664
CER	1601	HYD	330984	1/10/2008	RESALE OF PARTS ONLY	BECON LIGHTS	116	-	116
CER	1601	HYD	333508	1/25/2008	HYDRAULIC	INSTALL ACCUMULATOR	-	96	96
CER	1601	HYD	331416	2/11/2008	BOOM	BLOCK CRACKED HEAD SHEAVE	3,496	912	4,408
CER	1601	HYD	337847	2/28/2008	BOOM	REBUILD STEER CYLINDER.REPAIR BOOM PINNING PROBLEM	2,665	2,136	4,801
CER	1601	HYD	340104	2/28/2008	FRAME AND CHASSIS	REPLACE SUSPENSION ACCUMULATOR.REPAIR DROP BOX LEA	3,293	2,856	6,149
CER	1601	HYD	340098	2/28/2008	OUTRIGGERS	REPAIR OUTRIGGER PRESSURE TRANSDUCERS.REPAIR SUSPE	6,387	-	6,387
CER	1601	HYD	338317	3/25/2008	HYDRAULIC	REPLACE WORN OUT COUNTERWEIGHT CYLINDERS.BAD RODS.	17,036	864	17,900
CER	1601	HYD	349045	3/26/2008	PREVENTATIVE MAINTENANCE	PM ON UPPER NOT DUE AT 15943 HRS.	-	24	24
CER	1601	HYD	339993	3/27/2008	PREVENTATIVE MAINTENANCE	PM-B FILTER SERVICE ON LOWER	379	576	955
CER	1601	HYD	349381	4/4/2008	PREVENTATIVE MAINTENANCE	CHECK CRANE LEVELING	1,108	480	1,588
CER	1601	HYD	351191	4/16/2008	ENGINE	UPPER ENGINE TEMP LIGHT FLASHING AND WENT OFF.	111	264	375
CER	1601	HYD	352952	4/18/2008	ENGINE	NO START ON UPPER	188	48	236
CER	1601	HYD	351682	4/21/2008	PREVENTATIVE MAINTENANCE	REPLACE A2B PULL CABLE.REPLACE MISSING CABLE GUIDE	44	168	212
CER	1601	HYD	353152	5/2/2008	HYDRAULIC	HOIST ROUGH. COUNTERWEIGHT LIGHT NOT WORKING.	471	288	759
CER	1601	HYD	355937	5/7/2008	PREVENTATIVE MAINTENANCE	PM-A UPPER FILTER SERVICE AT 16028 HRS.	300	288	588
CER	1601	HYD	354136	5/7/2008	ENGINE	UPPER ENGINE OVERHEATING.REPAIR RADIATOR.THERMOSTA	3,505	2,688	6,193
CER	1601	HYD	356701	5/13/2008	INSPECTIONS	ANNUAL INSPECTION	275	-	275

Region	Unit #	Type	WO #	Date Closed	Labor Code	WO Description	\$ Parts	\$ Labor	\$ Total
CER	1601	HYD	364437	7/2/2008		TIRES REPLACED TIRES.LEFT SIDE 2ND AND 3RD AXLE.	4,750	192	4,942
CER	1601	HYD	368030	7/17/2008		PNEUMATIC SYSTEMS REPAIR AIR LEAK AT LOWER DRIVER SEAT.	-	144	144
CER	1601	HYD	368780	7/23/2008		HYDRAULIC REPAIR LOWER HYD LEAK	-	144	144
CER	1601	HYD	368628	7/29/2008		CAB AIR LEAK IN DRIVERS SEAT	158	-	158
CER	1601	HYD	378321	9/18/2008		PREVENTATIVE MAINTENANCE PM-A ON LOWER @3384 HRS	134	192	326
CER	1601	HYD	378323	9/18/2008		PREVENTATIVE MAINTENANCE PM-B FILTER SERVICE ON UPPER @ 16168 HRS	183	456	639
CER	1601	HYD	378771	9/24/2008		TIRES REPLACE TIRE	2,350	-	2,350
CER	1601	HYD	376964	10/14/2008		PREVENTATIVE MAINTENANCE LOWER:DOES NOT TRACK STRAIGHT ALL TIME.DOES NOT LE	1,117	888	2,005
CER	1601	HYD	383916	10/30/2008		COMPUTER SYSTEMS LICCON ERROR CODE 162 BASE ANGLE SENSOR	2,621	612	3,233
CER	1601	HYD	386913	11/7/2008		PREVENTATIVE MAINTENANCE PM-A FILTER SERVICE ON UPPER @ 16341 HRS	156	192	348
CER	1601	HYD	386934	11/12/2008		TIRES REPLACE TWO TIRES 2&3 RIGHT SIDE	2,350	120	2,470
CER	1601	HYD	387010	1/2/2009		PREVENTATIVE MAINTENANCE LOWER:1ST & 3RD STEER CYL LEAK.R.F.O.R.HOSE LEAK.	955	-	1,663
CER	1601	HYD	392019	1/2/2009		PREVENTATIVE MAINTENANCE RIGHT FRONT OUTRIGGER LEAKS.FRONT O.R.BEAM HAS OIL	1,911	1,416	3,327
CER	1601	HYD	390353	1/26/2009		PREVENTATIVE MAINTENANCE PM-B FILTER SERVICE ON LOWER NOT DUE AT 3548 HRS.	-	192	192
CER	1601	HYD	397548	1/26/2009		PREVENTATIVE MAINTENANCE PM-B ON UPPER @ 16511 HRS.	175	468	643
CER	1601	HYD	400127	2/13/2009		OUTRIGGERS CHECK/REPAIR LEFT FRONT OUTRIGGER BLEED DOWN.	4,276	492	4,768
CER	1601	HYD	393517	2/17/2009		COMPUTER SYSTEMS CHECK COMPUTER PROBLEM	9	528	537
CER	1601	HYD	404797	3/11/2009		FRAME AND CHASSIS SUSPENSION WILL NOT AUTO LEVEL CORRECTLY	468	-	468
CER	1601	HYD	412183	4/30/2009		COMPUTER SYSTEMS ERROR E11	-	384	384
CER	1601	HYD	413441	5/5/2009		INSPECTIONS ANNUAL CRANE INSPECTION	275	-	275
CER	1601	HYD	412702	5/11/2009		TIRES REPAIR/REPLACE TIRE RIGHT SIDE SECOND AXLE.	3,556	948	4,504
CER	1601	HYD	415107	5/19/2009		RIGGING RIGGING (4 SLINGS BLR 7X16)	699	-	699

# Work Order Estimate

Work Order #	205864
Branch	BMT
Bill to Branch	BMT
Customer Number	0
Equipment Model	LTM1225
Equipment Class	300
Description of Problem	
Work Order Desc.	LUFFING JIB MAST CYLINDER LEAKING
Reviewed by	Randy Johnston
Reviewers Comments	
Review Date	

Authorized By	Approved Rob Pearce
Authorized Date	
Created By	CHRISW
Date Opened	05/31/2006
Equipment Number	1601
Equipment Make	LIEBHERR
Equipment Category	60

	<i>Estimate</i>	<i>Actual</i>
Labor Total \$	\$0.00	\$192.00
Parts Total \$	\$15,389.03	\$11,889.03
Misc Charge	\$0.00	\$0.00
<b>Total \$</b>	<b>\$15,389.03</b>	<b>\$12,081.03</b>

## Labor

Labor					
999		0	\$0.00	4	\$192.00
4639	LUBE LUFFING CYLINDERS	0	\$0.00	0	\$0.00
Totals:		0	\$0.00	4	\$192.00

## Parts

Parts					
HC	HYDRAULIC COMPONENTS	1	\$14,285.00	1	\$10,785.00
SK	SEAL KIT	1	\$1,104.03	1	\$1,104.03
Totals:		2	\$15,389.03	2	\$11,889.03

## Other

Other					
	Nothing Found				
Totals:					

# Work Order Estimate

Work Order #	338317
Branch	FRE
Bill to Branch	FRE
Customer Number	0
Equipment Model	LTM1225
Equipment Class	300
Description of Problem	CYLINDERS HAVE BEEN REBUILT 8 MONTHS AGO.KITS ARE 1/3 PRICE OF CYLINDERS.
Work Order Desc.	REPLACE WORN OUT COUNTERWEIGHT CYLINDERS.BAD RODS.
Reviewed by	Randy Johnston
Reviewers Comments	
Review Date	02/01/2008

Authorized By	Approved Rob Pearce
Authorized Date	02/04/2008
Created By	VERNB
Date Opened	02/04/2008
Equipment Number	1601
Equipment Make	LIEBHERR
Equipment Category	60

	<i>Estimate</i>	<i>Actual</i>
Labor Total \$	\$576.00	\$864.00
Parts Total \$	\$18,036.34	\$17,036.34
Misc Charge	\$0.00	\$0.00
<b>Total \$</b>	<b>\$18,612.34</b>	<b>\$17,900.34</b>

## Labor

Labor						
6021	REMOVE OR INSTALL COUNTERWEIGHTS	12	\$576.00	18	\$864.00	
		Totals:	12	\$576.00	18	\$864.00

## Parts

Parts						
	FREIGHT ON PARTS	1	\$1,000.00	0	\$0.00	
BP	HYD BOOM PARTS	2	\$17,036.34	2	\$17,036.34	
		Totals:	3	\$18,036.34	2	\$17,036.34

## Other

Other					
	Nothing Found				
		Totals:			