

Maxim Crane Works, LP

5 Year Maintenance History Summary

2709

175 ton

GROVE GMK5175

1996

Maxim performs scheduled Preventative Maintenance ("PMs) procedures at least every 90 days and more periodically depending on crane usage. Maxim performs a comprehensive crane inspection at each PM interval, before and after each crane rental and annually in accordance with OSHA and ANSI requirements. Maxim installed its computerized maintenance management system in 2004, attached is a standard cost summary of workorders documented since system installation. All workorders exceeding \$10,000, representing rebuild activities and major component replacement, are attached for review.

Region	Unit #	Type	WO #	Date Closed	Labor Code	WO Description	\$ Parts	\$ Labor	\$ Total
WER	2709	HYD	6592	7/10/2003	PREVENTATIVE MAINTENANCE	VALVE STEM LEAKING AIR	-	96	96
WER	2709	HYD	6293	7/11/2003	PREVENTATIVE MAINTENANCE	HARD TO START	-	216	216
WER	2709	HYD	10778	8/18/2003	PREVENTATIVE MAINTENANCE	AIR LEAK HYD LEAK	-	240	240
WER	2709	HYD	14634	9/15/2003	PREVENTATIVE MAINTENANCE	AIR SYSTEM	-	336	336
WER	2709	HYD	14401	9/15/2003	PREVENTATIVE MAINTENANCE	SERVICE UPPER AND LOWER	7	456	463
WER	2709	HYD	7559	9/16/2003	HYDRAULIC	HYD LEAK	348	192	540
WER	2709	HYD	15354	10/3/2003	PREVENTATIVE MAINTENANCE	AIR LEAK	-	312	312
WER	2709	HYD	29087	12/9/2003	ELECTRICAL	LIGHTS	-	48	48
WER	2709	HYD	21355	12/17/2003	PREVENTATIVE MAINTENANCE	AIR LEAK	3,753	2,376	6,129
WER	2709	HYD	31789	1/5/2004	PREVENTATIVE MAINTENANCE	UPSTAIRS BATTIRES	155	264	419
WER	2709	HYD	29901	1/20/2004	PREVENTATIVE MAINTENANCE	BOOM LEAKING HYD-FUEL PUMP UPSTAIRS R&R	-	768	768
WER	2709	HYD	40721	3/3/2004	PREVENTATIVE MAINTENANCE	SERVICE UPPER	31	312	343
WER	2709	HYD	45565	4/8/2004	PREVENTATIVE MAINTENANCE	SERVICE	185	576	761
WER	2709	HYD	53431	4/20/2004	BRAKES	BRAKE ADJ	-	72	72
WER	2709	HYD	54221	5/13/2004	ELECTRICAL	LIGHT CORD	-	192	192
WER	2709	HYD	59673	6/16/2004	ELECTRICAL	LIGHTS	-	72	72
WER	2709	HYD	64644	6/24/2004	HOIST / WINCH	ASSEMBLE BALL	-	168	168
WER	2709	HYD	58180	6/24/2004	PREVENTATIVE MAINTENANCE	CK & ADJ BRAKES	-	672	672
WER	2709	HYD	66251	8/30/2004	ORIENTATION	BRAKE VALVE LEAKS	1,048	2,712	3,760
WER	2709	HYD	82964	9/29/2004	ELECTRICAL	4-WAY FLASHERS,TACH.	-	1,668	1,668
WER	2709	HYD	93655	12/6/2004	WELDING	DRIVE SHAFT-FRAME	93	3,684	3,777
WER	2709	HYD	97224	12/13/2004	BOOM	MANBASKET	-	432	432
WER	2709	HYD	102168	2/7/2005	ENGINE	RUNS SLOW,WATER IN FUEL?	185	2,208	2,393
WER	2709	HYD	91069	2/22/2005	PREVENTATIVE MAINTENANCE	SERVICE	424	1,656	2,080
WER	2709	HYD	119642	3/30/2005	ELECTRICAL	A2B PLUG/WAS NOT WRITTEN UP/CRANE OUT ON JOBS	-	108	108
WER	2709	HYD	121457	4/7/2005	PREVENTATIVE MAINTENANCE	SERVICE/UPPER	100	96	196
WER	2709	HYD	120101	4/7/2005	ENGINE	FUEL THROTTLE AND COMPUTER LENGTH POT/ TIRE REPAIR	202	1,722	1,924
WER	2709	HYD	121984	4/11/2005	ENGINE	FUEL LEAK ON LOWER ENGINE,LIGHTS,BRAKE ADJUST	-	228	228
WER	2709	HYD	128927	5/16/2005	ORIENTATION	SERVICE CALL/ AIR LEAK	-	72	72
WER	2709	HYD	131851	5/25/2005	TIRES	MOUNT TIRES (4)	847	-	847
WER	2709	HYD	132615	6/2/2005	HYDRAULIC	BLOWN HYD.HOSE	-	144	144
WER	2709	HYD	132618	6/2/2005	ORIENTATION	SERVICE CALL/ FITTING FOR AIR TANK BROKE OFF	-	288	288
WER	2709	HYD	126566	6/3/2005	ELECTRICAL	LIMIT SWITCH IN TURNTABLE BROKEN	556	1,056	1,612
WER	2709	HYD	133998	6/7/2005	TIRES	TIRES	4,849	-	4,849
WER	2709	HYD	140144	7/18/2005	PREVENTATIVE MAINTENANCE	OUTREP/REPAIR SEAT CUSHON , NEW GRILL	290	-	290
WER	2709	HYD	143729	7/28/2005	ELECTRICAL	INSTALL NEW BLOWER MOTOR ASSY.	154	-	154
WER	2709	HYD	116887	9/1/2005	PREVENTATIVE MAINTENANCE	PM-A SERVICES	164	-	164
WER	2709	HYD	151267	9/19/2005	ELECTRICAL	JOYSTICK	2,028	48	2,076
WER	2709	HYD	163738	10/28/2005	INSPECTIONS	ANNUAL INSPECTION	450	-	450
WER	2709	HYD	165358	11/4/2005	CAB	INSTALL JOY STICK	-	96	96
WER	2709	HYD	116888	11/9/2005	PREVENTATIVE MAINTENANCE	PM-B SERVICES	39	432	471
WER	2709	HYD	175219	12/20/2005	FRAME AND CHASSIS	SUSPENSION	-	528	528
WER	2709	HYD	176097	12/22/2005	DRIVE TRAIN	WON'T GO INTO GEAR	-	540	540
WER	2709	HYD	177542	1/10/2006	PREVENTATIVE MAINTENANCE	REMOVE FUEL TANK	-	1,632	1,632
WER	2709	HYD	151148	1/11/2006	PREVENTATIVE MAINTENANCE	PM-A SERVICES	55	240	295
WER	2709	HYD	180106	1/27/2006	ELECTRICAL	ELECTRICAL	-	192	192
WER	2709	HYD	178075	1/27/2006	PREVENTATIVE MAINTENANCE	DISSASSEMBLE HYD.TANK	2,336	924	3,260
WER	2709	HYD	181860	1/28/2006	PNEUMATIC SYSTEMS	LOWER BRAKE PROBLEM	779	144	923
WER	2709	HYD	187843	2/23/2006	ENGINE	FUEL CAP	36	-	36
WER	2709	HYD	196093	3/24/2006	ENGINE	REPLACE TRANSMISSON FILTER	27	84	111

Region	Unit #	Type	WO #	Date Closed	Labor Code	WO Description	\$ Parts	\$ Labor	\$ Total
WER	2709	HYD	196957	4/28/2006	PREVENTATIVE MAINTENANCE	MISC C4'S	54	876	930
WER	2709	HYD	204439	5/2/2006	ENGINE	A/C BRACKET	-	216	216
WER	2709	HYD	179722	5/2/2006	PREVENTATIVE MAINTENANCE	PM-A SERVICES	172	504	676
WER	2709	HYD	205264	5/11/2006	ENGINE	FUEL PROBLEMS	-	96	96
WER	2709	HYD	207206	5/31/2006	ENGINE	FUEL PROBLEM AND LIGHTS	58	288	346
WER	2709	HYD	210652	5/31/2006	HYDRAULIC	BOOM LEAK	332	1,272	1,604
WER	2709	HYD	213822	6/15/2006	INSPECTIONS	INSPECT	-	696	696
WER	2709	HYD	122490	6/19/2006	INSPECTIONS	90 DAY CAL OSHA INSPECTION	-	216	216
WER	2709	HYD	205019	6/19/2006	PREVENTATIVE MAINTENANCE	PM-A SERVICES	33	216	249
WER	2709	HYD	215333	6/28/2006	PREVENTATIVE MAINTENANCE	REPAIRS FROM INSPECTION	16	168	184
WER	2709	HYD	224707	8/7/2006	ELECTRICAL	NON START	13	852	865
WER	2709	HYD	226272	8/10/2006	DRIVE TRAIN	CARRIER BEARING	-	168	168
WER	2709	HYD	227992	8/18/2006	ELECTRICAL	ALTERNATOR	685	204	889
WER	2709	HYD	226880	9/13/2006	PREVENTATIVE MAINTENANCE	CARRIER BEARING SUPPORT BRACKET,BOLTS,	-	2,160	2,160
WER	2709	HYD	238575	10/2/2006	WELDING	WELDING REPAIRS	-	60	60
WER	2709	HYD	166778	10/11/2006	PREVENTATIVE MAINTENANCE	PM-B SERVICES	121	288	409
WER	2709	HYD	241783	10/24/2006	INSPECTIONS	ANNUAL CRANE INSPECTION(CERT)	425	-	425
WER	2709	HYD	247540	11/10/2006	TIRES	CHECK TIRES ON TRAILERS (6616,6360,6595)	65	-	65
WER	2709	HYD	247551	11/10/2006	INSPECTIONS	ANNUAL INSPECTION (CERT) RE-INSPECTION	175	-	175
WER	2709	HYD	249500	11/29/2006	HYDRAULIC	TRANS, ELEC, HYD.	45	396	441
WER	2709	HYD	240891	12/5/2006	BOOM	RE-SEAL BOOM CYLINDER	4,932	4,800	9,732
WER	2709	HYD	251252	12/7/2006	ELECTRICAL	DASH LIGHTS	-	24	24
WER	2709	HYD	253582	12/11/2006	TIRES	FLAT REPAIR	215	-	215
WER	2709	HYD	253317	12/18/2006	DRIVE TRAIN	CHECK DRIVETRAIN AND TRANS	-	72	72
WER	2709	HYD	250407	12/19/2006	CABLE/WIRE	REPLACE MAIN WIRE	3,420	432	3,852
WER	2709	HYD	253340	1/11/2007	PREVENTATIVE MAINTENANCE	HOIST CONTROLS,LIFTING RAMS,DASH LIGHT,WELD CRACKS	330	744	1,074
WER	2709	HYD	258405	2/2/2007	INSPECTIONS	90 DAY CAL OSHA INSPECTION	-	108	108
WER	2709	HYD	262138	2/2/2007	PREVENTATIVE MAINTENANCE	BUBBLE LEVEL	73	192	265
WER	2709	HYD	241099	2/2/2007	PREVENTATIVE MAINTENANCE	PM-A SERVICE	103	264	367
WER	2709	HYD	264396	2/9/2007	DRIVE TRAIN	RETARDER STUCK NO THROTTLE	107	144	251
WER	2709	HYD	266012	2/15/2007	WELDING	WELD CRACKS AND AIR LEAK	-	480	480
WER	2709	HYD	266699	2/19/2007	WELDING	WELD PIN	-	288	288
WER	2709	HYD	266999	2/20/2007	WELDING	REPAIR LADDERS	-	144	144
WER	2709	HYD	276423	4/6/2007	PREVENTATIVE MAINTENANCE	PAINT EQUIPMENT	500	-	500
WER	2709	HYD	284122	5/15/2007	TIRES	FLAT REPAIR	93	-	93
WER	2709	HYD	284638	5/22/2007	DRIVE TRAIN	DRIVE LINE AND AIR LEAKS	-	240	240
WER	2709	HYD	284367	5/23/2007	DRIVE TRAIN	DRIVELINE PROBLEMS	-	144	144
WER	2709	HYD	275169	6/5/2007	PREVENTATIVE MAINTENANCE	EXHAUST SYSTEM	-	264	264
WER	2709	HYD	289946	6/15/2007	HYDRAULIC	HYD LEAK	-	144	144
WER	2709	HYD	263554	6/23/2007	INSPECTIONS	90 DAY CAL OSHA INSPECTION	-	96	96
WER	2709	HYD	263556	6/23/2007	PREVENTATIVE MAINTENANCE	PM-A SERVICE	91	288	379
WER	2709	HYD	290775	8/17/2007	PREVENTATIVE MAINTENANCE	REPAIRS FROM INSPECTION	227	492	719
WER	2709	HYD	302971	8/24/2007	DRIVE TRAIN	REPLACE DRIVE SHAFT	1,694	540	2,234
WER	2709	HYD	305465	9/4/2007	TIRES	SUDDUTH INSTALLED 4 TIRES	9,007	-	9,007
WER	2709	HYD	291662	9/20/2007	INSPECTIONS	90 DAY CAL OSHA INSPECTION	-	96	96
WER	2709	HYD	311738	10/3/2007	INSPECTIONS	QUAD	425	144	569
WER	2709	HYD	314710	10/23/2007	CABLE/WIRE	HYD. LEAK	-	348	348
WER	2709	HYD	307743	10/31/2007	PREVENTATIVE MAINTENANCE	REPAIR FROM INSPECTION	142	168	310
WER	2709	HYD	319825	11/9/2007	INSPECTIONS	RE-INSPECTION FOR CERTIFICATION	131	-	131
WER	2709	HYD	318104	11/9/2007	OUTRIGGERS	OUTRIGGER LEAK	-	192	192

Region	Unit #	Type	WO #	Date Closed	Labor Code	WO Description	\$ Parts	\$ Labor	\$ Total
WER	2709	HYD	312298	11/9/2007	HYDRAULIC	REPAIRS FROM INSPECTION(HYD LEAK)	306	240	546
WER	2709	HYD	316815	11/9/2007	PAINTING	PAINT BOOM	-	1,176	1,176
WER	2709	HYD	317496	11/9/2007	FABRICATION	FAB NEW DOLLY MOUNT	-	1,740	1,740
WER	2709	HYD	312994	11/12/2007	BOOM	REBUILT TELESCOPE CYLINDER	63,645	16,188	79,833
WER	2709	HYD	291659	11/16/2007	PREVENTATIVE MAINTENANCE	PM-A SERVICE	-	48	48
WER	2709	HYD	322319	12/7/2007	PREVENTATIVE MAINTENANCE	REFINERY REPAIRS	-	768	768
WER	2709	HYD	319955	12/7/2007	OUTRIGGERS	AIR LEAK,ELECTRICAL,KEY	394	900	1,294
WER	2709	HYD	330692	1/10/2008	ELECTRICAL	WON'T START	-	144	144
WER	2709	HYD	333102	1/28/2008	ELECTRICAL	A2B	153	600	753
WER	2709	HYD	334218	3/5/2008	BOOM	BOOM PIN	467	708	1,175
WER	2709	HYD	343915	3/13/2008	BOOM	JIB AND CAB FAN	-	492	492
WER	2709	HYD	348806	3/26/2008	ELECTRICAL	REPLACE BATTERIES	-	264	264
WER	2709	HYD	241098	4/18/2008	PREVENTATIVE MAINTENANCE	PM-B SERVICES	81	468	549
WER	2709	HYD	309027	4/21/2008	INSPECTIONS	90 DAY CAL OSHA INSPECTION	-	192	192
WER	2709	HYD	351786	4/21/2008	ENGINE	FUEL LEAK AND OTHER REPAIRS	109	288	397
WER	2709	HYD	352848	4/21/2008	OUTRIGGERS	CHANGE OUTRIGGER HOSES	-	1,200	1,200
WER	2709	HYD	354018	5/1/2008	ELECTRICAL	NON START / HOSES	1,434	-	1,434
WER	2709	HYD	355101	5/6/2008	PREVENTATIVE MAINTENANCE	LUBE DRIVE LINE	-	180	180
WER	2709	HYD	356044	5/17/2008	ENGINE	NO START	-	852	852
WER	2709	HYD	341364	5/20/2008	ELECTRICAL	REPLACE STARTER	485	144	629
WER	2709	HYD	356027	6/17/2008	PREVENTATIVE MAINTENANCE	DIFFERENTIAL LOCK	89	-	89
WER	2709	HYD	358024	7/2/2008	ENGINE	REPLACE BUSHINGS, COOLANT LEAK	220	528	748
WER	2709	HYD	367195	7/11/2008	TIRES	TIRE BLOW-OUT ON DOLLY	449	-	449
WER	2709	HYD	367197	7/18/2008	TIRES	TIRE REPAIR	81	-	81
WER	2709	HYD	368810	8/1/2008	FABRICATION	FAB CRIBBING RACK FOR CRANE	-	192	192
WER	2709	HYD	370386	8/14/2008	PREVENTATIVE MAINTENANCE	SERVICE DUE UPPER AND LOWER	47	384	431
WER	2709	HYD	374666	8/28/2008	ELECTRICAL	CHECK DOLLY AND CRANE LIGHTS	-	192	192
WER	2709	HYD	373227	8/29/2008	COMPUTER SYSTEMS	COMPUTER PROBLEM	321	792	1,113
WER	2709	HYD	370444	9/16/2008	PNEUMATIC SYSTEMS	AIR LEAK'S	-	192	192
WER	2709	HYD	376620	9/16/2008	ENGINE	FIRE IN LOWER ENGINE COMPARTMENT	5,362	3,780	9,142
WER	2709	HYD	377995	10/31/2008	HYDRAULIC	REPAIR FIRE DAMAGE ON LOWER	5,863	3,300	9,163
WER	2709	HYD	387187	11/14/2008	PNEUMATIC SYSTEMS	REPLACE BAD AIR TANK DRAINS	41	-	41
WER	2709	HYD	386840	11/14/2008	COMPUTER SYSTEMS	CHECK COMPUTER AND JOYSTICK FUNCTION'S	-	384	384
WER	2709	HYD	386047	11/14/2008	HYDRAULIC	STEERING PROBLEM	-	528	528
WER	2709	HYD	379782	11/14/2008	INSPECTIONS	RECENT DUE ANNUAL	450	384	834
WER	2709	HYD	379485	12/1/2008	HYDRAULIC	PARTIAL CRANE REBUILD	75,191	10,404	85,595
WER	2709	HYD	387741	12/5/2008	DRIVE TRAIN	DRIVE TRAIN NOISE AND HYD LEAKS	551	2,064	2,615
WER	2709	HYD	390284	12/12/2008	PREVENTATIVE MAINTENANCE	OIL SAMPLE DUE	-	48	48
WER	2709	HYD	389549	12/12/2008	DRIVE TRAIN	POSSIBLE PROBLEM WITH SPEED SENSOR	2,755	192	2,947
WER	2709	HYD	389364	12/16/2008	CAB	REPAIR HEATER SYSTEM IN UPPER CAB	175	192	367
WER	2709	HYD	393103	12/22/2008	ENGINE	UPPER THROTTLE PROBLEM'S	-	144	144
WER	2709	HYD	393199	1/9/2009	PREVENTATIVE MAINTENANCE	REPLACE BAD CLAMP	149	48	197
WER	2709	HYD	397597	1/28/2009	INSPECTIONS	ENGINE INFORMATION	-	192	192
WER	2709	HYD	396154	1/28/2009	ENGINE	FUEL DEL PROBLEM	-	384	384
WER	2709	HYD	402072	2/20/2009	ENGINE	UPPER QUIT RUNNING	-	120	120
WER	2709	HYD	403197	3/6/2009	INSPECTIONS	SMOKE TEST	-	144	144
WER	2709	HYD	406737	3/20/2009	ENGINE	REPALCE BAD AIR CLEANER	30	-	30
WER	2709	HYD	405576	3/20/2009	PREVENTATIVE MAINTENANCE	SERVICE UPPER	9	192	201
WER	2709	HYD	408923	4/10/2009	TIRES	FLAT TIRE ON CRANE	216	-	216
WER	2709	HYD	412360	5/1/2009	PREVENTATIVE MAINTENANCE	LOWER ENGINE DUE SERVICE	33	192	225

Region	Unit #	Type	WO #	Date Closed	Labor Code	WO Description	\$ Parts	\$ Labor	\$ Total
WER	2709	HYD	410857	5/1/2009	ELECTRICAL	C4 HIT LIST	-	384	384
WER	2709	HYD	413318	5/15/2009	DRIVE TRAIN	FILTER HOUSING FELL OFF CRANE	64	288	352
WER	2709	HYD	413428	5/15/2009	PREVENTATIVE MAINTENANCE	REPIAR STEERING TIE ROD BAR	488	576	1,064

Work Order Estimate

Work Order #	312994
Branch	LON
Bill to Branch	LON
Customer Number	0
Equipment Model	GMK5175
Equipment Class	175
Description of Problem	
Work Order Desc.	REBUILT TELESCOPE CYLINDER
Reviewed by	Rob Pearce
Reviewers Comments	
Review Date	10/10/2007

Authorized By	Approved Neil Goodale
Authorized Date	10/11/2007
Created By	KHEINZE
Date Opened	10/11/2007
Equipment Number	2709
Equipment Make	GROVE
Equipment Category	60

	<i>Estimate</i>	<i>Actual</i>
Labor Total \$	\$0.00	\$16,188.00
Parts Total \$	\$16,000.00	\$63,645.05
Misc Charge	\$0.00	\$0.00
Total \$	\$16,000.00	\$79,833.05

Labor

Code	Description	Hours	Rate	Total Hours	Total Amount
5333	R&R TELESCOPE CYLINDER	0	\$0.00	287	\$16,188.00
Totals:		0	\$0.00	287	\$16,188.00

Parts

Code	Description	Quantity	Unit Price	Total Quantity	Total Amount
BH	HYD BOOM SECTION	1	\$16,000.00	0	\$0.00
HB	HYD BOOM CYLINDER	0	\$0.00	2	\$55,525.00
HC	HYDRAULIC COMPONENTS	0	\$0.00	1	\$191.31
SL	SEAL	0	\$0.00	2	\$7,056.87
SV	SHEAVE	0	\$0.00	2	\$871.87
Totals:		1	\$16,000.00	7	\$63,645.05

Other

Code	Description	Hours	Rate	Total Hours	Total Amount
	Nothing Found				
Totals:					

Work Order Estimate

Work Order #	379485
Branch	FON
Bill to Branch	FON
Customer Number	0
Equipment Model	GMK5175
Equipment Class	175
Description of Problem	
Work Order Desc.	PARTIAL CRANE REBUILD
Reviewed by	Rob Pearce
Reviewers Comments	
Review Date	09/25/2008

Authorized By	Approved
Neil Goodale	Neil Goodale
Authorized Date	09/26/2008
Created By	JOHNWARD
Date Opened	09/30/2008
Equipment Number	2709
Equipment Make	GROVE
Equipment Category	60

	Estimate	Actual
Labor Total \$	\$13,104.00	\$10,404.00
Parts Total \$	\$154,585.84	\$75,191.02
Misc Charge	\$0.00	\$0.00
Total \$	\$167,689.84	\$85,595.02

Labor

2960	INSPECT CONDITION OF HOSES AND TUBING OUTRIGG	80	\$3,840.00	27	\$1,296.00
3070	CHANGE HOSES	24	\$1,152.00	4	\$192.00
4726	R&R ENGINE	65	\$3,120.00	56	\$2,688.00
5132	R&R BRAKES	40	\$1,920.00	40.5	\$1,944.00
5317	R&R BOOM HOIST CYLINDER	0	\$0.00	2	\$96.00
5336	R&R TRANSMISSION	40	\$1,920.00	12	\$576.00
5345	REMOVE & REPACK HOIST CYLINDER	16	\$768.00	20	\$960.00
5472	REBUILD COUNTERWEIGHT CYLINDER	8	\$384.00	27.5	\$1,404.00
6020	TRAVEL TIME TO AND FROM SERVICE CALL	0	\$0.00	8	\$576.00
6385	REMOVE DROP BOX	0	\$0.00	8	\$384.00
6387	INSTALL DROP BOX	0	\$0.00	6	\$288.00
Totals:		273	\$13,104.00	211	\$10,404.00

Parts

	OUTSIDE REBUILD	0	\$0.00	1	\$18,250.50
	OUTSIDE REBUILD	0	\$0.00	1	\$5,913.50
	OUTSIDE PAINTING	0	\$0.00	1	\$16,192.74
	OUTSIDE REBUILD	0	\$0.00	1	\$10,875.00
	OUTSIDE-HOSE	0	\$0.00	1	\$6,004.07
	OUTSIDE PAINTING	0	\$0.00	1	\$3,353.50
	OUTSIDE REBUILD	1	\$24,000.00	0	\$0.00
	OUTSIDE REBUILD	1	\$13,000.00	0	\$0.00
	OUTSIDE PAINTING	1	\$28,000.00	0	\$0.00
	OUTSIDE REBUILD	1	\$32,000.00	0	\$0.00
	OUTSIDE REBUILD	2	\$8,000.00	0	\$0.00
	OUTSIDE-HOSE	1	\$6,000.00	0	\$0.00
BR	BRAKES	50	\$30,510.30	30	\$5,650.00
DT	DRIVETRAIN	0	\$0.00	1	\$0.00
EN	WHOLE ENGINES	0	\$0.00	1	\$0.00
HC	HYDRAULIC COMPONENTS	21	\$8,626.20	20	\$245.00
HS	HOSES	16	\$1,004.59	16	\$1,428.46
PM	PUMP	0	\$0.00	1	\$3,031.38
SK	SEAL KIT	2	\$2,549.11	2	\$2,700.95
SL	SEAL	2	\$895.64	10	\$1,545.92
Totals:		98	\$154,585.84	87	\$75,191.02

Other